


Announcement

Product Discontinuation of SIL-HV

(amended 2nd version)



Dear customer,

Hereby we would like to inform you about discontinuation of the following product:

SIL-HV Series – High Voltage Reed Relay

Items affected:

SIL05-1x85-76LxK	SIL05-1A85-76DxK
SIL05-1x85-77LxK	SIL05-1A85-77DxK
SIL12-1x85-76LxK	SIL12-1A85-76DxK
SIL12-1x85-77LxK	SIL12-1A85-77DxK

Reason for Discontinuation:

Due to new improvements of internal design and electric parameters, this complete series is to be replaced by a second generation of High Voltage SIL Relays - SHV Series.

Discontinuation Date:

31. December 2015

Last Time Order Date:

30. September 2015

Replacement / Alternative Product:

New SHV Series is a direct replacement of the discontinued relays with the layout 76 regarding the layout, outer dimensions and electric parameters. Please note a higher Pull-In Voltage for the 5V coil nominal voltage. Exact values can be found in the product datasheet.

The layout 77 is to be discontinued without a replacement.

For the replacement search, please refer to the table on the page no. 2.

Support:


For technical questions or sample requests, please contact Mr David Stastny dstastny@standexmeder.com

David Stastny
Product Manager

Arndt Werlich
Chief Technology Officer

Ralf Maier
Chief Business Officer

Announcement Product Discontinuation



SIL-HV Series – High Voltage Reed Relay

Table of discontinued items with their direct replacements

Discontinued Item	Replacement Item
SIL05-1A85-76L2K	SHV05-1A85-78L2K (available in Q4/2015)
SIL05-1A85-76L3K	SHV05-1A85-78L3K
SIL05-1A85-76D2K	SHV05-1A85-78D2K (available in Q4/2015)
SIL05-1A85-76D3K	SHV05-1A85-78D3K
SIL05-1A85-76L4K	SHV05-1A85-78L4K
SIL05-1A85-76D4K	SHV05-1A85-78D4K
SIL12-1A85-76L3K	SHV12-1A85-78L3K
SIL12-1A85-76D3K	SHV12-1A85-78D3K
SIL12-1A85-76L4K	SHV12-1A85-78L4K
SIL12-1A85-76D4K	SHV12-1A85-78D4K
SIL05-1A85-77LxK	no replacement available
SIL05-1A85-77DxK	no replacement available
SIL12-1A85-77LxK	no replacement available
SIL12-1A85-77DxK	no replacement available